



Timer #1



Timer #2



Timer #3



Timer #4



Timer #5



Weather Sensor #1



08-27-2026 07:57AM PDT

Weather Sensor #2



08-27-2026 08:28AM PDT

Weather Sensor #3



08-27-2026 09:00AM PDT

Weather Sensor #4



08-27-2026 10:07AM PDT

Weather Sensor #5



Master Valve and Flow Sensor Install Backflow #1





Wire for Master and Flow Sensor Backflow #1





Backflow #2



09-01-2026 03:27PM PDT

Very depth, main line,



09-01-2026 03:28PM PDT



09-02-2026 07:05AM PDT



09-02-2026 01:33PM PDT





Wires preparation for Wire Ride



Old sprinklers replaced





Master Valve and Flow Sensor Backflow #2





09-16-2026 12:25PM PDT

Backflow #2 completed



09-16-2026 01:12PM PDT



09-16-2026 03:06PM PDT



09-17-2026 08:07AM PDT

Lateral leak we repaired to have all grass system working



09-17-2026 11:47AM PDT

Wire Ride Installed, (timer #4)



09-17-2026 11:47AM PDT



09-22-2026 07:14AM PDT



09-22-2026 07:15AM PDT



All Toro heads were replaced into Rain Bird and we replaced all sprayer nozzles into Toro Precision Spray Nozzles